ULPOWER AERO ENGINES N.V.

Kasteelstraat 37 B-8980 Geluveld Belgium

Tel. +32 57 46 82 22

Fax +32 57 46 82 57

e-mail: info@ulpower.com



Service Bulletin No. 2013-02

SUBJECT: Alternator fan

MODELSAFFECTED: All models

TIME OF COMPLIANCE Before next flight

AFFECTED SERIAL NUMBER: All engines

Reason

See service bulletin 2012-01

The new design is without welding.

Between the 2 parts are distance rings. A longer bolt (M6x30) keep the parts on place and fix them to the starter ring gear (see parts catalogue)



Picture 1 picture 2

Inspection

Check if the engine is equipped with a fan conform picture 1 and 2.

Action

If necessary, change the old type fan by the new one. Safety

Observe all warnings and cautions contained in the airplane manuals.



SB 2013-02							
Issued			Revised			Page	Revision
Мо	Day	Year	Мо	Day	Year	1 of 1	0
11	08	2013				. 3	J